


Option 2

- Option 2 will bring the building up to current building codes and accessibility standards.
- This option includes an addition on the west side of the library. This addition provides a larger, more accessible elevator, improves the basement exit, and allows the existing south stair to become more open to the main floor of the library.
- Some improvements allow for better programs and services. A new service desk and two new tutorial rooms are added on the main floor level. In the basement, walls are removed to make the children's area more open. Computer workstations are relocated to make space for a reading playground.
- The Class 4 (-30% to +60%) cost estimate for this option is **\$7.5 million**.

Option 2 - Exterior Upgrades



↑ Site Plan



Garbage enclosure



Accessible parking stall upgrades



Elevator & stair addition



New roofing



New concrete landings & stairs



New concrete landings & ramp

*Images shown are representative only

Option 2 - Exterior View



Option 2 - Interior Upgrades



*Images shown are representative only

Option 2 - Interior Upgrades




Staff office Universal and barrier-free washrooms



New addition: elevator New addition: exit stair



Future reading playground



Stair safety upgrades



Accessible kitchenettes & closets



Secure south entry & open stair

↑ Basement

- | | | | | | |
|----|-------------------------|-----|-----------------------|-----|----------------------------|
| 1. | Program Room | 7. | Mechanical Room | 13. | New Elevator |
| 2. | Staff Room | 8. | Electrical Room | 14. | New Exit Stair |
| 3. | Children's Area & Books | 9. | Existing Exit Stair | 15. | Open Stair |
| 4. | Storage Room | 10. | Existing Washrooms | 16. | Computer Area |
| 5. | Staff Office | 11. | Barrier-free Washroom | 17. | Future Literacy Playground |
| 6. | Service Corridor | 12. | Universal Toilet Room | | |

*Images shown are representative only