



Underside of Omand Park pedestrian bridge. Cracks to bridge deck. Taken June 12, 2017



The Structure is Fully Submerged/Flooded. Taken May 6, 2020



**Underside of Omand Park pedestrian bridge. Separation of bridge deck.
Taken May 17, 2021**



East pier of Omand Park pedestrian bridge. Bulging in bearings. Taken May 17, 2021



**Top of Omand Park pedestrian bridge. Cracks to bridge deck.
Taken July 17, 2019x**